

RELEASE NOTES

EFI™ is pleased to announce the release of Fiery® proServer and Fiery XF 7.1.3. Version 7.1.3 is a server update for Fiery proServer and Fiery XF 7.1, updating the Fiery XF server from 7.1, 7.1.1 or 7.1.2 to 7.1.3.

Bug fixes

- FAST RIP-related fixes:
 - Fixed a problem that caused a shift in the cut of nesting jobs with K-Cut marks on a DYSS cutter.

- Printer-driver-related fixes:
 - Fixed a problem of missing print modes in the device capabilities for EFI™ VUTEK® printers, which are required for workflow integration.
 - Fixed a problem setting up the total ink limit for Roland VersaUV LEF-300 GIW.
 - Fixed a problem with print modes for Gandinnovations Jeti 3150 UV.
 - Fixed a problem creating a calibration for EPSON® Stylus Pro 5000 with CMYKOG inks.
 - Fixed a problem with vacuum settings for Mimaki UCJV-150-160 CMYK LUS-170/175.
 - Fixed a problem with stripes in the output for HP DesignJet Z9 printer.
 - Fixed a problem with print jobs that exceeded the printable area for HP DesignJet Z9.
 - Fixed a problem connecting to an HP Latex 3000.

- FAST DRIVE printer-driver-related fixes:
 - Fixed a problem printing the total ink limit chart for the EFI VUTEK 5r+ [FAST DRIVE] printer driver.
 - Fixed a problem with white ink VCC processing for all [FAST DRIVE] printer drivers.
 - Fixed a problem with 100% white ink coverage for all [FAST DRIVE] printer drivers.

- Nesting-related fixes:
 - Fixed a problem with file dimension shrinkage in Step & Repeat.

- Fiery XF server-related fixes:
 - Fixed a problem of slow processing of nestings.
 - Fixed a problem that prevented JobFolder from being deleted when Delete All was selected in Server Manager > Server > Maintenance.
 - Fixed a problem with Summa F-Series cutting of small jobs.
 - Fixed a problem with Step & Repeat when the job was larger than the selected media.

New printer drivers

- EPSON
 - EPSON SureColor SC-S60600L CT
 - EPSON SureColor SC-S80600L CT

Updated printer drivers

- EFI
 - EFI Pro 30f
 - Added "PrographicsUV Ultra" ink support
 - Added file output option
 - EFI VUTEk 3r / 3r+ / 5r / 5r+ / Pro 32r [FAST DRIVE] and EFI VUTEk 3r / 3r+ / 5r / 5r+ / Pro 32r
 - Added "SuperFlex XF" ink support
 - EFI VUTEk 32h [FAST DRIVE]
 - Added "EFI GSLX Pro" ink support
 - EFI Pro 32r [FAST DRIVE] and EFI Pro 32r
 - Added new print modes:
 - White-Under Production
 - White-Under DS
 - White
 - White DS
 - Updated print modes (changed x resolution):
 - High Quality
 - White-CWC
 - White-CWBWC-C1
 - White-CWBWC-C2
 - EFI VUTEk FabriVUi
 - Listed as a separate printer model now with a different default gap definition of 10 mm between rows for calibration and profiling charts for supported measuring devices (see "Color features" below)

Updated cutter drivers

- MATIC
 - MATIC Helios Plus laser cutter
 - Support of randomized cut marks distribution

Productivity features

- Enhanced custom media size handling (also requires Fiery Command WorkStation Package 6.4.0.321 or higher).

Color features

- Chart generation with gap definition support between rows for calibration and profiling charts for the following measuring devices:
 - EFI ES-2000
 - X-Rite i1Pro2
 - Barbieri Spectro LFP
 - Barbieri Spectro LFP qb

Helps avoid color patch contamination caused by the gassing effect of the EFI FabriVUi printer with inline calendar (EFI VUTEk FabriVUi printer default gap value: 10 mm; all other printer models: 0 mm).

Requires Fiery Color Profiler Suite 5.2 or higher and Fiery Command WorkStation Package 6.4.0.321 or higher.

Availability

- The Fiery XF 7.1.3 server update is available via an online update through Fiery Server Control for all configurations of Fiery proServer and Fiery XF version 7.1.
- Alternatively, the version 7.1.3 server update can be downloaded from the [EFI downloads area](#).



Note!

- All bug fixes, new and updated printer and cutter drivers, as well as features described above, are delivered with the Fiery XF server 7.1.3 update. Where there are exceptions, these are noted with the particular feature.
- Fiery proServer and Fiery XF solutions are made up of multiple software applications. A server application (Fiery XF server), a client application (Fiery Command WorkStation®), plus color applications (Color Profiler Option and Color Verifier Option included as part of Color Profiler Suite). Only the server application is updated as part of the 7.1.3 update, and the other software components may need to be updated to work correctly with the latest update.
- The following overview informs you about the required Fiery XF server, Fiery Command WorkStation and Color Profiler Suite versions for full support of the feature set provided with Fiery XF 7.1.3:

	Fiery XF server	Fiery Command WorkStation Package	Fiery Color Profiler Suite
Fiery XF 7.1.3	7.1.3	6.4.0.321 or higher	5.2 or higher

- The latest versions of Fiery Command WorkStation and Fiery Color Profiler Suite are available via the Fiery Software Manager or via the download center at <https://www.efi.com/support-and-downloads/download-center>.

Software Maintenance & Support Agreement (SMSA) and EFI Enhanced Service Program (ESP)

EFI Software Maintenance & Support Agreements (SMSA) and Enhanced Service Program (ESP) agreements for Fiery proServer and Fiery XF provide an ongoing stream of features, improvements, fixes and the latest printer drivers. Fiery XF 7.1.x is available at no additional charge for all customers with their Fiery software covered under one of these agreements.

For more information, please contact your local Fiery proServer or Fiery XF dealer, or visit www.efi.com/fiery-for-inkjet.

EFI's portfolio of integrated solutions increase productivity and improve your bottom line. Find out more at www.efi.com.

